



HEAT SHIELD GREASE

Saving costs for shields.

Grease will make strong heat shield barrier on the front shield of the torch and cover the parts effectively against melted spatter, which are destroying the parts.

Grease is highly effective also for MIG torches.

Ref. No. T-12777

Using: apply by paintbrush in strong cover to front shield, do not clean shield orifices, blowing gas will make it itself.



THERMACUT[®]
THE CUTTING COMPANY

SALES DEPARTMENT THERMACUT, K.S.
DUKELSKÁ 76A, ŠENOV U NOVÉHO JIČINA 742 42
TEL.: +420 556 423 440
E-MAIL: SALES@THERMACUT.CZ
WWW.THERMACUT.COM